



HYUNDAI

NEW THINKING.
NEW POSSIBILITIES.

Technical Service Bulletin

GROUP

BODY

NUMBER

14-BD-001-1

DATE

JULY 2014

MODEL(S)

ALL

SUBJECT: LEATHER STEERING WHEEL CLEANING


THIS TSB SUPERSEDES TSB #14-BD-001 to update the service procedure and warranty information.

Description:

Some vehicles may exhibit dirt or buildup on the leather steering wheel. If any of these conditions are found, do not replace the steering wheel. Instead, follow the cleaning procedure described below.

NOTICE

The procedure in this bulletin is not covered under Factory Warranty.



Applicable Vehicles:

- All vehicles equipped with leather steering wheels.

Circulate To: General Manager, Service Manager, Parts Manager, Warranty Manager, Service Advisors, Technicians, Body Shop Manager, Fleet Repair


Parts Information:

Supplies can be sourced through local markets.

| Description | Contents |
|--|---|
| 3M Leather & Vinyl Restorer 39040 or Equivalent |  |
| 3M Scotchbrite Cleaning Pad 7439 or Equivalent |  |
| 3M Microfiber Cloth 6016 or Equivalent |  |
| Disposable Latex or Nitrile Gloves |  |

Cleaning Procedure:

1. Spray the leather restorer onto the cleaning pad and scrub the steering wheel.



2. Using the microfiber cloth, wipe any leftover residue with a clean portion of the cloth.



CAUTION

Do not leave the steering wheel wet or slippery. Wipe any residue off of the steering wheel.



Steering wheel shown partially cleaned to demonstrate cleaning results.

