



**NUMBER:** 05-003-13

**GROUP:** Brakes

**DATE:** February 28, 2013

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.*

**THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 13-015. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN'S HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.**

**SUBJECT:**

Front And/Or Rear Brake Noise (Squeal)

**OVERVIEW:**

This bulletin involves changing front and rear brake pads to correct a brake squeal noise.

**MODELS:**

2013 (LD) Charger

**NOTE: This bulletin applies to vehicles in police fleet usage only (sales code AHB) built before November 29, 2012 (MDH 1129XX).**

**SYMPTOM/CONDITION:**

The customer may experience a squealing noise during braking coming from the front and/or rear of the vehicle.

**DIAGNOSIS:**

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. For all other customers that describe the symptom/condition, perform the Repair Procedure.

**PARTS REQUIRED:**

Qty.	Part No.	Description
1	68147681AA	PAD KIT, Front Disc Brake (Contains Pads and Slippers)
1	68001440AB	PAD KIT, Rear Disc Brake

**REPAIR PROCEDURE:**

**NOTE: Be sure to review all warnings and cautions before proceeding, refer to the detailed information available in DealerCONNECT> TechCONNECT under: Service Info> 05- Brakes - Warning and 05- Brakes - Caution.**

1. Raise the vehicle on a suitable hoist. Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: Service Info> 04- Vehicle Quick Reference> Hoisting> Standard Procedure> Hoisting.
2. Remove and replace front brake pads (p/n 68147681AA). Refer to the detailed removal procedures available in DealerCONNECT> TechCONNECT under: Service Info> 05- Brakes> Brakes, Base> Hydraulic/Mechanical> Pads, Brake, Front> Removal/Installation.
3. Remove and replace rear brake pads (p/n 68001440AB). Refer to the detailed removal procedures available in DealerCONNECT> TechCONNECT under: Service Info> 05- Brakes> Brakes, Base> Hydraulic/Mechanical> Pads, Brake, Rear> Removal/Installation.

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

<b>Labor Operation No:</b>	<b>Description</b>	<b>Amount</b>
05-70-22-9D	Pads, Disc Brake - Replace Front and Rear (2 - Skilled)	0.8 Hrs.

**FAILURE CODE:**

ZZ	Service Action
----	----------------