XM Re-Registration with Radio Unit Swap

USA

Audio/Visual/Telematics

Audio/Video

2010-2014 Models with Satellite Radio

### APPLICABLE VEHICLES

2010-2014	Camry	2011-2014	FJ Cruiser
2011-2014	Highlander	2010-2014	Prius
2010-2014	Tundra	2011-2014	Sienna
2013-2014	Avalon HV	2012-2014	RAV4 EV
2010-2011, 2013-	Land Cruiser	2012-2014	Prius V
2014		a de la companya de l	
2010-2014	4Runner	2010-2014	Sequoia
2011-2014	Avalon	2012-2014	RAV4
2010-2014	Venza	2012-2014	Prius PHV
2012-2014	Tacoma	2012-2014	Prius C
2011-2014	Highlander HV	2010-2014	Camry HV
2011-2014	Corolla		

## CONDITION

To receive satellite radio functions after the initial trial period has expired, the customer must enter into a contract with XM Satellite Radio Inc. After entering into a contract, registration of an 8-digit XM Radio ID is required. This 8-digit XM Radio ID is found by turning to channel "0" of the satellite radio.

When a new radio head unit is installed in a vehicle, the XM registration does not automatically transfer to the new radio unit.

#### RECOMMENDATIONS

Before removing the old radio, record the original XM Radio ID from channel "0" of the satellite radio. When the radio is replaced, the new XM Radio ID must be re-registered through XM Satellite Radio Inc. The new XM Radio ID is also found on channel "0" of the new satellite radio.

Re-registration can be done by calling SiriusXM Dealer Support at 1-800-852-9696.

- Provide the old Radio ID and ask to transfer the service on this radio to the new Radio ID. Confirm with the agent that the old Radio ID has been deactivated.
- Confirm which services are being transferred (e.g. Audio only or Audio and Traffic and TravelLink.)
- Ask the SXM Dealer Support Agent to send an activation signal to the new radio and confirm the radio is working. If necessary, dealer can perform the signal refresh by entering the new Radio ID into the SiriusXM Radio Signal Refresh Website (See Linked Reference #1).

Expires on

08/27/2014

© 2013, Toyota Motor Sales, USA

Page 1 of 2

Ver. 2.1 8/28/2011 T



**Tech Tip** T-TT-0250-13

August 27, 2013

Subject

# XM Re-Registration with Radio Unit Swap

USA

Applicabili

2010-2014 Models with Satellite Radio

# LINK REFERENCES

1. SiriusXM Radio Signal Refresh Website (www.siriusxm.com/oemrefresh)