



---

Date: 11/26/2013 Ref. number: Parts / Action - Special Return / G\_0000180113  
Subject: **Special Return - Fuel Pump Assembly Part Number 15821962**

---

To: Chevrolet, Buick, GMC, and Cadillac Dealers

**DESCRIPTION:**

Requesting return of Fuel Pump Assembly part number 15821962 with a date code range of A2 (January 2012) through E3 (May 2013) on the merchandise label. Good stock will be F3 or higher.

**EFFECTIVE DATE:**

Immediately through February 28, 2014

**ORDER INPUT:**

For replacement parts please order the same part number, GM part number 15821962. All GMCCA Distribution Center Inventory has been replaced.

**GENERAL INFORMATION:**

Mail, email or fax a separate PC659 Application for each return to your Administrative PDC and indicate:

1. Type of return - check "12"
2. Comments column - "reference GlobalConnect Action Return message number G\_0000180113"

---

Message Attachment(s):

[PC659.pdf](#) Acrobat PDF (129.1KB)

[11-26-13 Copy of this message G\\_0000180113 - Special Return of Fuel Pump Assembly Part Number 15821962.pdf](#) Acrobat PDF (16.29KB)

---

Contact name: Bruce English

E-Mail: [bruce.a.english@gm.com](mailto:bruce.a.english@gm.com)

Department: Parts - Customer Care &  
Aftersales WHQ

Phone: 810-606-4351

Intended roles: Parts Manager, Service Manager

Archives: 12/26/2013

Expires: 11/26/2019