



# Service Bulletin

File in Section: -

Bulletin No.: PIP4896D

Date: August, 2013

## PRELIMINARY INFORMATION

**Subject:** PQC Part Restriction Control Solenoid WBody And TCM Valve Assembly And Valve Body Parts Restriction

**Models:** 2008 - 2012 Cadillac Escalade  
2008 - 2012 Chevrolet Silverado, Tahoe  
2008 - 2012 GMC Sierra, Yukon  
Equipped with 2ML70 Transmission RPO M99

**This PI was superseded to remove parts from restriction. Please discard PIP4896C.**

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

The Control Solenoid (w/ Body and TCM) Valve Assembly Part Number 24255209 and Valve Body Part Number 29544409 have been removed from the PQC parts restriction effective 08/13/2012. Calls to the PQC are no longer necessary.

Your cooperation with this program is greatly appreciated.

### Recommendation/Instructions

General Motors Engineering would like to thank the dealers that participated in the PQC Control Solenoid W/Body And TCM Valve Assembly And Valve Body Parts Restriction.

Please follow the published service information diagnostics and if your diagnostics lead to TEHCM or Valve Body replacement, parts can be ordered through your parts department.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.