



Service Bulletin

File in Section: -

Bulletin No.: PIC5857A

Date: July, 2013

PRELIMINARY INFORMATION

Subject: PQC Part Restriction - Airbag Sensing and Diagnostics Module

Models: 2003-04 Pontiac Vibe

This PI was superseded to change restriction from TAC to PQC. Please discard PIC5857.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

As part of our ongoing quality improvement efforts, the following Airbag Sensing and Diagnostics Modules are currently restricted through PQC:

19205561 - Airbag Sensing and Diagnostics Module (without side airbags)

19205562 - Airbag Sensing and Diagnostics Module (with side airbags)

Recommendation/Instructions

Before considering replacement of the Airbag Sensing and Diagnostics Module, please review the latest version of Field Action 13030, document all of your results, and repair as necessary. If the concern is still present or if the diagnosis leads to replacement of the Airbag Sensing and Diagnostics Module, contact PQC to review your test results.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.