



# Service Bulletin

File in Section: -

Bulletin No.: PIC4299A

Date: June, 2013

## PRELIMINARY INFORMATION

**Subject:** Diagnostic Tip - Paint Code Used To Refinish The Underside Of The Rear Hatch Or Decklid

**Models:** 2005 - 2014 Chevrolet Corvette

**This PI was superseded to add 2008-14 model years. Please discard PIC4299.**

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

Some Body Shop Technicians may comment that they cannot locate the "Low Gloss" paint code that is used to paint the underside / interior of a rear hatch or decklid.

### Recommendation/Instructions

Use paint code WA167A to paint these areas.

### Warranty Information

There is not a labor time or labor operation associated with this PI because the labor time is considered part of the original repair.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.