

Technical Service Bulletin Number	Revision Level	Date	Group Number
TSB110249			



Technical Service Bulletin

Subject

Vee-Ribbed Drive Belt Change in Water Pump Drive Option WP9429

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

A new vee-ribbed drive belt has been introduced as part of a product improvement. It supersedes the old vee-belt. The new vee-belt is visibly shorter than the old vee-belt.

The old and new part numbers are shown below. Option WP9429 contains the new vee-ribbed drive belt, Part Number 3289716.

New Part Number	Old Part Number
3289716	3289746

This is a product improvement **not** subject to campaign or TRP actions.

Document History

Date	Details
2011-8-24	Module Created
2014-3-25	Part number change

Last Modified: 27-Mar-2014