

Technical Service Bulletin Number	Revision Level	Date	Group Number
TSB140083			



Technical Service Bulletin

Subject

High-Pressure Fuel Pump Service Parts for ISX15 CM2250

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

The purpose of this document is to announce the release of the service part numbers for the fuel pump head barrel and plunger, and the fuel pump roller tappets.

Use Procedure 005-227 in the appropriate manual for instructions to remove the fuel pump head and replace the fuel pump roller tappets. **Only** perform the necessary steps in the procedure to replace the roller tappets.

Use the Fuel Pump Head Barrel and Plunger Replacement, Installation Instruction 4908166, to install the new barrel and plungers.

Use Table 1 if the engine is equipped with a two cylinder, two piston fuel pump. Use Table 2 if the engine is equipped with a three cylinder, two piston fuel pump. Use Table 3 for the ISX12/ISX11.9/QSX11.9 engines.

Table 1, Parts for Two Cylinder, Two Piston Pump (ISX15/QSX15)		
Description	Part Number	Quantity
Barrel and Plunger Assembly	4327258	2

Fuel Pump Head Gasket	2872513	1
Roller Tappet	2872226	2

Table 2, Parts for Three Cylinder, Two Piston Pump (ISX15/QSX15)

Description	Part Number	Quantity
Barrel and Plunger Assembly	4327258	2
Fuel Pump Head Gasket	4984478	1
Roller Tappet	2872226	2

Table 3, Parts for ISX12/ISX11.9/QSX11.9 Pump

Description	Part Number	Quantity
Barrel and Plunger Assembly	4327258	2
Fuel Pump Head Gasket	4954753	1
Roller Tappet	2872226	2

Document History

Date	Details
2014-6-20	Module Created

Last Modified: 23-Jun-2014

Copyright © 2000-2010 Cummins Inc. All rights reserved.