

Service Magazine

Media Number -M0068796-00

Publication Date -22/02/2016

Date Updated -22/02/2016

i06599940

Coolant Pipe Leaks on Certain CT660 On Highway Trucks {7000, 7304}

SMCS - 7000; 7304

On Highway Truck

CT660S (S/N: TGA1-UP; TGD1-UP; TJD1-UP; TEJ1-UP; TRK1-UP; TKL1-UP; TEM1-UP; TEP1-UP; TGS1-UP; TJS1-UP; TGT1-UP; TSW1-UP; TEY1-UP; TSY1-UP; TEZ1-UP; TGZ1-UP)

Description Of Change: The new coolant pipe with support bracket has been updated to be more robust and improved service life.

Adaptable To: Replace with updated part number **479-1591** Kit-Heater if failure occurs. The old part number **398-5451** Kit-Heater can still be used if the **479-1591** Kit-Heater part number is unavailable. For either part ordered, verify the white marking on the end of heater pipe. The white marking indicates that the pipe has been pressure tested and is of the updated welding process.

[View Image](#)



Illustration 1 g06042616
Verify the white marking on the end of heater pipe in call out 1

The effective serial numbers are listed in Table 1.

Table 1

Effective Serial Numbers
S/N:TEJ00299-UP
S/N:TEM00113-UP
S/N:TEP02005-UP
S/N:TEY00184-UP
S/N:TEZ00103-UP
S/N:TGA01569-UP
S/N:TGD00158-UP
S/N:TGS00145-UP
S/N:TGT00108-UP
S/N:TGZ00002-UP
S/N:TJD00105-UP
S/N:TJS00002-UP
S/N:TKL00600-UP
S/N:TRK01566-UP
S/N:TSW00002-UP
S/N:TSY00144-UP