

Classification:

EL16-030

Reference:

ITB16-030

COPYRIGHT© NISSAN NORTH AMERICA, INC.

Date:

August 4, 2016

2016 QX60; SOME AUTOMATIC BACK DOOR DTC DESCRIPTIONS ARE NOT DISPLAYED ON CONSULT-III PLUS

APPLIED VEHICLE: 2016 QX60 (L50)
2016 QX60 Hybrid (L50)

SERVICE INFORMATION

The descriptions for Automatic Back Door DTCs in the table below do not display on CONSULT-III plus (C-III plus). Only the DTC alphanumeric designation is displayed.

Use the table below to identify the DTC description and its listing in the Electronic Service Manual (ESM) or ASIST.

DTC shown in C-III plus	DTC Description (Not shown on C-III Plus)	ASIST I-KEY tab of CONSULT Codes	ESM DLK (Door & Lock) section table of content
B2426	SPINDLE SENSOR LH	B2426 ENCODER	B2426 ENCODER
B2427	SPINDLE SENSOR RH	B2427 ENCODER	B2427 ENCODER
B2428	AUTOMATIC BACK DOOR CONTROL UNIT	B2428 AUTOMATIC BACK DOOR CONTROL UNIT	B2428 AUTOMATIC BACK DOOR CONTROL UNIT
B242A	CLOSURE CONDITION	B242A CLOSURE CONDITION	B242A CLOSURE CONDITION

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.