

SSM 46016	Some 2016-2017 Expedition and Navigator vehicles built on or before 08/12/2016 and 2016 F150 vehicles built on or before 08/09/2016 equipped with Sirius satellite radio may exhibit an intermittent concern where the audio cuts out and the radio displays a No Signal message while driving in open sky conditions in certain locations in your area. This may be due to interference with cellular phone tower signals. If a vehicle displays this condition near cellular phone towers, replace the audio unit antenna with part number GL1Z-10E893-AC on Expedition/Navigator and HL3Z-10E893-AA for F150. Refer to Workshop Manual(WSM), Section 415-00 for removal and installation instructions. Use applicable labor operation(s)in the SLTS Manual Section 11.
--------------	---