Reference	SSM72508
Models	F-PACE / X761
	F-TYPE / X152
	XE / X760
	XF / X250
	XF / X260
	XJ / X351
Title	Reminder to follow the Battery Storage Process detailed in Topix
Category	Electrical
Last modified	06-Nov-2015 00:00:00
Symptom	203000 Basic Electrical
Content	Issue
	Vehicles battery claims for battery discharged.
	Cause
	The battery storage process has not been correctly followed upon vehicle delivery and following a PDI.

## Action

Please refer to Topix section- Battery Care.