

Subject: CORRECT APPLICATION FOR ATF M-V (TYPE M5), MERCON®V, MERCON®LV, AND JWS3309 (T-IV) AUTOMATIC TRANSMISSION FLUIDS	Bulletin No: 05-002/13
	Last Issued: 03/11/2013

BULLETIN NOTE

- This bulletin supersedes the previous bulletins 05-002/13 issued on 3/4/13, 05-002/11 issued on 02/23/11 and 05-005/08 issued on 04/11/08. The APPLICABLE MODEL(S)/VINS, DESCRIPTION, and AUTOMATIC TRANSMISSION FLUID SERVICE APPLICATION have been revised.
- Changes are noted below in Red beside the change bar.

APPLICABLE MODEL(S)/VINS

2011-2013 Mazda2	2007-2012 CX-7	2000-2009 B-Series A/T
2004-2013 Mazda3 (NON SKYACTIV)	2007-2013 CX-9	2006-2013 MX-5
2006-2013 Mazda5	2001-2011 Tribute	2006-2011 RX-8
2003-2013 Mazda6	2008-2009 Tribute HEV	

DESCRIPTION

Always be sure to use the correct automatic transmission fluid when replacing ATF. Using the wrong ATF may cause shift quality complaints or may even damage the transmission.

NOTE:

- ATF M-V (TYPE M5) IS NOT THE SAME FLUID AS MERCON®V OR MERCON®LV ATF.
- ATF M-V (TYPE M5) HAS A GREATER VISCOSITY THAN MERCON®V AND MERCON®LV ATF IN LOW TEMPERATURES.
- ATF M-V (TYPE M5) HAS A GREATER ANTI-JUDDER SPECIFICATION THAN MERCON®V AND MERCON®LV ATF.
- TRANSMISSION FLUID FLUSHING SHOULD ONLY BE PERFORMED WHEN INSTRUCTED BY THE WORKSHOP MANUAL OR ANY OTHER MAZDA PUBLICATION.

CAUTION:

- USING ATF OTHER THAN ATF M-V (TYPE M5) IN AUTOMATIC TRANSMISSIONS DESIGNED TO USE ATF M-V (TYPE M5) MAY CAUSE SHIFT QUALITY COMPLAINTS.
- USING ANY OTHER ATF OTHER THAN THE SPECIFIED ATF IN AUTOMATIC TRANSMISSIONS MAY CAUSE TRANSMISSION DAMAGE.
- USING A GENERIC, MULTI-PURPOSE OR UNIVERSAL ATF MAY CAUSE TRANSMISSION DAMAGE.
- DAMAGE TO THE TRANSMISSION CAUSED BY USING THE INCORRECT ATF, OR A GENERIC, MULTI-PURPOSE OR UNIVERSAL ATF WILL NOT BE COVERED BY WARRANTY. Refer to the following chart, the Owner's Manual, or MS3 for ATF specifications.

AUTOMATIC TRANSMISSION FLUID SERVICE APPLICATION

Refer to the following table to determine the correct automatic transmission fluid.

Model	Required Service Fluid	Mazda Part Number
2011-2013 Mazda2	ATF M-V (TYPE M5)	0000-77-112E-01
2004-2013 Mazda3 (NON SKYACTIV)	ATF M-V (TYPE M5)	0000-77-112E-01
2006-2013 Mazda5	ATF M-V (TYPE M5)	0000-77-112E-01
2003-2008 Mazda6 2.3L	ATF M-V (TYPE M5)	0000-77-112E-01
2009-2013 Mazda6 2.5L	ATF M-V (TYPE M5)	0000-77-112E-01
2009-2013 Mazda6 3.7L	JWS3309 (T-IV)	0000-77-114E-01
2003-04 Mazda6 3.0L (5-speed A/T)	ATF M-V (TYPE M5)	0000-77-112E-01
2005-08 Mazda6 3.0L (6-speed A/T)	JWS3309 (T-IV)	0000-77-114E-01
2007-2012 CX-7 2.3L Turbo	JWS3309 (T-IV)	0000-77-114E-01
2010-2012 CX-7 2.5L	ATF M-V (TYPE M5)	0000-77-112E-01
2007-2013 CX-9	JWS3309 (T-IV)	0000-77-114E-01
2006-2011 RX-8	JWS3309 (T-IV)	0000-77-114E-01
2006-2013 MX-5	JWS3309 (T-IV)	0000-77-114E-01
2000-2009 B-Series	MERCON®V ATF	0000-77-120E-05
2001-08 Tribute (CD4E 4-speed A/T)	MERCON®V ATF	0000-77-120E-05
2009-11 Tribute (6F35 6-speed A/T)	MERCON®LV ATF	0000-77-122E-01
Tribute HEV	MERCON®V ATF	0000-77-120E-05