



© 2014 Mazda Motor of America, Inc.

Subject: DTC B2278 STORED IN THE POWER STEERING CONTROL MODULE	Bulletin No: 06-001/14
	Last Issued: 07/14/2014

BULLETIN NOTE

- SERVICE BULLETIN 06-001/14, "2008-2011 TRIBUTE - DTC B2278 STORED IN THE POWER STEERING CONTROL MODULE", IS NO LONGER VALID.
- SERVICE BULLETIN 06-001/14 HAS BEEN SUPERSEDED BY SAFETY RECALL 7614E, "2008-2011 TRIBUTE - ELECTRIC POWER-ASSISTED STEERING (EPAS)."

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.