

**Product Update: Audio-Navigation Unit****AFFECTED VEHICLES**

<b>Year</b>	<b>Model</b>	<b>Trim</b>	<b>VIN Range</b>
2016	Pilot	ALL with Navigation	Check the iN VIN status for eligibility

**BACKGROUND**

There is a software problem within the audio-navigation unit that may cause the display screen to go blank and the unit to stop working.

**This bulletin will be revised in the future once the repair procedure, tool information, and warranty claim information are available.**

**CUSTOMER INFORMATION:** The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.