

Reference	SSM72372
Models	Discovery Sport / L550
Title	L550 Discovery Sport Hood/Bonnet seals visually defective
Category	Body
Last modified	13-Aug-2015 00:00:00
Symptom	110000 Sealing
Attachments	Hood seals.pdf
Content	<p>Issue: Retailers are replacing hood/bonnet seals (see Fig.1 & 2 of attached illustrations) that are visually different between left and right hand side.</p> <p>Affected part numbers are:</p> <ul style="list-style-type: none">• LR076984• LR076973 <p>Cause: One seal appears to be damaged (Fig. 3) when compared to the other (Fig. 4). It appears deformed in shape, with wrinkles/creases (Fig. 3).</p> <p>Action: The physical characteristics are not impaired by this visual difference therefore the seal(s) do NOT require replacing.</p>

Fig. 1




Fig. 2



Fig. 3




Fig. 4

