



Service Bulletin

03-065

Section

Instruments/Gauges - 03

Description

Fix As Fail - Model 320/520 May Require a CECU Update and Wiring Repair

Release Date

3/8/2019

Introduction

Peterbilt has determined in certain Models 320 and 520 vehicles built with NAMUX software part numbers P30-1032-XXX and not updated to P30-1030-XXX (-109 or greater) in the field require an ESA update.

A CECU software update has been released; [reference 03-067](#) for the CECU update procedure to version P30-1030-XXX.

After the CECU has been updated to P30-1030-XXX, use procedure below to modify the seatbelt warning circuit or the seat belt warning will be active in the display regardless of seat belt status.

Resolution

Fix As Fail

Follow the procedure on bulletin [03-067](#) to verify NAMUX software and install the software update if required.

Follow the procedure below to modify the seatbelt warning indicator harness to fix the persistent seat belt warning indicator.

Warranty

Through standard warranty or for repairs completed by 04/01/2020, Peterbilt will pay for labor to correct wiring (software updates, file under 03-067):

- 0.3 hours labor to find and label the wires for the persistent seat belt indicator. File a quick Claim Code 03-065.
- File an additional claim for extraordinary circumstances. A quick claim for standard labor must be filed first.

For Field...	Enter...
Failure Location	003-001-082
Failure Type	125
Claim Type	N
Campaign Number	03065
SRT 003-065	<u>0.30 hours labor to correct the wiring for persistent seatbelt indicator.</u>

Parts

No parts, disconnecting wires only

Procedure

[03-065 Persistent Seat Belt Light Procedure](#)

Attachments

Authored by: DKH

Access to PACCAR's Enterprise Portal is provided as a benefit of doing business with PACCAR. All applications and content accessed through this system are confidential and proprietary and the property of PACCAR Inc and its suppliers, and must be kept strictly confidential pursuant to the contract licensing such access. Disclosure, publication, release or distribution of any material found on PACCAR systems to any person other than employees with a need to know such information is strictly prohibited. All activity on this system is monitored. If PACCAR suspects or discovers any unauthorized activity, access may be immediately terminated without prior notification. Violators may be subject to legal action.

© Copyright 2019 PACCAR Inc. All rights reserved. We welcome your [feedback](#) on this page. For technical questions or concerns about this page, please contact the [DealerNet Webmaster](#).