



**AUTOMOBILE DIVISION**  
American Honda Motor Co., Inc.  
1919 Torrance Blvd., - P.O. Box 2215  
Torrance, CA 90509-9870

December 2014

RE: 2014 Accord Plug-In

Dear Honda Accord Plug-In Owner:

**What is the reason for this notice?**

Our records indicate that a PRODUCT UPDATE has not been completed on this vehicle; refer to the address card for the affected VIN. On some 2014 Accord Plug-Ins, the PCM (powertrain control module) software may allow conditions that could damage the E-VTC (electronic variable timing control) actuator. To minimize the probability for damage to occur, a software update for the E-VTC is available. Even if you do not feel a problem has occurred, you should still have the software updated. Otherwise, the E-VTC may be damaged.

**What should you do?**

Please contact any authorized Honda dealer to schedule a service appointment. The dealer will update your vehicle *free of charge*.

**If you have questions**

If you have any questions about this notice, or you need assistance locating a dealer, contact Honda Automobile Customer Service at 888-234-2138 and select option 2. You may also find this information at [www.Hondacars.com](http://www.Hondacars.com).

We apologize for any inconvenience this safety recall may cause you. We are taking this action in the interest of your safety and continued satisfaction with your Honda vehicle.

Sincerely,

**American Honda Motor Co., Inc.**  
**Honda Automobile Division**

**NOTICE: If this is a leased vehicle, please forward this notice to the lessee.**

FOR DEALER USE ONLY: REFERENCE SVC BULLETIN #13-102

JC6

Diciembre del 2014

RE: Accord Plug-In 2014

Estimado propietario de un vehículo Honda Accord Plug-In:

**¿Cuál es el motivo de esta notificación?**

Nuestros registros indican que no se ha completado una ACTUALIZACIÓN DE PRODUCTO en este vehículo; consulte la tarjeta de dirección para ver el VIN afectado. En algunos vehículos Accord Plug-In 2014, el programa del PCM (módulo de control del tren de mando [tren motriz] puede permitir condiciones que pudieran dañar el actuador E-VTC (control de sincronización variable electrónico). Para minimizar la probabilidad de que ocurra este daño, una actualización del programa para el E-VTC está disponible. Aunque usted no sienta que ha ocurrido un problema, usted todavía debería actualizar el programa. De lo contrario, el E-VTC se podría dañar.

**¿Qué debe hacer?**

Por favor comuníquese con cualquier concesionario autorizado Honda para programar una cita de servicio. El concesionario actualizará su vehículo *sin costo alguno*.

**Si tiene preguntas**

Si tiene preguntas acerca de esta notificación o necesita asistencia para ubicar un concesionario, comuníquese con Atención al Cliente de Automóviles Honda al 888-234-2138 y seleccione la opción 2. Usted también puede encontrar esta información en [www.Hondacars.com](http://www.Hondacars.com).

Le pedimos disculpas por cualquier inconveniente que esta campaña de seguridad pudiera causarle. Nosotros estamos tomando esta acción en el interés de su seguridad y satisfacción continua con su vehículo Honda.

Atentamente,

**American Honda Motor Co., Inc.  
División Automotriz de Honda**

**AVISO: Si este es un vehículo arrendado, por favor envíe esta notificación al arrendatario.**