Service Bulletin - Product



Roadranger

Subject: HLA Service and Repair Tools

Document Number: TMIB0254

Date: November 4, 2013

Description:

New service and repair tools are available for the HLA system. The tool offering includes a pump fastener tool, accumulator gas and fluid port service tools, nitrogen charge kit, and valve core torque tool.

Affected Models/Population:

All current HLA systems in service

Field Strategy:

Tools can be purchased through the Roadranger / K-Line tool distributor. Go to Roadranger.com/tools and click the Specialty Service Tools link, or go directly to KLineind.com to order.

HLA Tool Kit:

- RR1025HY Fluid port spanner wrench
- RR1026HY Gas port spanner wrench
- RR1019HY Bladder Pull Rod
- RR1023HY Fluid port wrench
- RR1027HY Nitrogen Charge Kit
- RR1020HY Gas valve torque wrench
- RR1024HY HLA Pump Tool

Warranty Information: None

The material contained in this bulletin is product improvement information. Eaton is not committed to, or liable for, canvassing existing products.