

## HONDA Tech Line Summary Article

September 2016 ATS 160902 Version 1

## **Bubbling/Blistering Paint on White-Colored Front Bumpers**

## **AFFECTED VEHICLES**

2016 HR-V

Is the paint bubbling/blistering on white-colored front bumpers? Some bumpers also show pink blotches in the same

We're aware of this issue and have it under investigation. At this time, contact your DPSM for further evaluation. In most cases, the bumper will need to be repainted.

© 2016 American Honda Motor Co., Inc. - All Rights Reserved