

Subject		Market
<b>Warranty Replacement of Non-OEM Headlamps</b>		USA
Service Category	Section	
Vehicle Exterior	Lighting (ext)ext)	
Applicability		
2013-2015 RX350		

**APPLICABLE VEHICLES**

2013-2015

RX350

**CONDITION**

Some vehicles with aftermarket headlamps (non OEM) are being repaired/replaced under warranty with OEM equipment.

**RECOMMENDATIONS**

When investigating customer complaints related to Headlamp issues (e.g. inoperative, intermittent function, open circuit, water entry, etc.), please verify that the Headlamp assembly is an OEM (not aftermarket) component.

OEM components can be identified by the presence of the markings shown below. Parts without these markings should be considered aftermarket components and not subject to Warranty replacement.

**OEM Headlamp Identification Markings  
(P/N: 81110 and 81150)****“NAL” lettering on the front lens.****“TOYOTA” lettering on the back side**



Subject	Market
<b>Warranty Replacement of Non-OEM Headlamps</b>	USA
Applicability	
2013-2015 RX350	

**LINK REFERENCES**

This Tech Tip does not contain any link references