



Tech Tips

TT 91-16-10

Date: June 24, 2016

2016 Golf, GTI, Golf R, Golf Sportwagon, eGolf, Passat, Jetta, CC, Tiguan, Beetle, Beetle Convertible – Display Reads “Please insert a data storage device with valid navigation data”. DTC B126CF2: “Navigation System Navigation Database not Enabled” may also be stored

November 4, 2016: Update to Information.

It is possible that the wrong version navigation SD card is with the car. Also, when replacing a radio or J794, the new unit may require a different version navigation SD card. There are **currently 3 part # suffixes available, “R”, “AC” and “B”**. Install the other suffix SD card that is currently with the car, clear any faults in address word 5F and perform a hard reboot on the radio (hold radio power down for 10-20 seconds) to restore navigation function.