## Next Unread Message

# **View Message**

Sent on	01 19 2016 <b>Expires on</b> 02 02 2016
From	Parts and Service Division
Subject	Request for Parts: 2015 TLX Brake Judder

## PRIORITY/ACTION REQUIRED

To: All Acura Service Managers/Consultants
From: Technical Research & Support Group
RE: Request for Parts: 2015 TLX Brake Judder

This message is solely directed to Acura dealership personnel; please handle accordingly. Print this *iN* message and provide a copy to the Shop Foreman and all Service Consultants.

## **Background**

American Honda (AHM) is investigating certain 2015 TLXs with a customer complaint of brake judder.

To fully understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to you attempting a repair of any kind.

#### Qualifiers

AHM is interested ONLY if the vehicle meets the following requirements:

- 1. Must be able to duplicate the judder.
- 2. No previous repair relating to the front brakes.

## **Action Required**

If you have or know of such a vehicle, please call the Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.