

[Next Unread Message](#)**View Message**

Sent on 09 04 2015 **Expires on** 12 02 2015
From Campaign Administration
Subject Product Update: 2014-15 Accord FHEV CVS Error Detection Update

DATE: September 4, 2015

TO: All Honda Sales, Service & Parts Managers and Personnel

FROM: Campaign Administration

Re: Product Update: 2014-15 Accord FHEV CVS Error Detection Update

Today, September 4, 2015, American Honda is announcing a product update for 6,786 Accord FHEV vehicles to update the high pressure battery cell monitoring system (CVS).

Basic Problem

The CVS software may not be sufficiently tough against electrical noise from the inverter and motor circuits. This may cause the vehicle to default to a fail-safe EV-only mode, reducing power output.

The Repair

Update CVS with enhanced software.

Service Bulletin

Service bulletins 15-057, *Product Update: IMA Cell Voltage Sensor (CVS) Software* has been posted to the Service Information System today in support of this campaign. It includes software, warranty and update information related to this product update.

Software Information

HDS Software Version:

3.016.033 or later

Control Module (CM) Update:

Application Version V3.01.42 or later

Database Update 25 Jun 2015 or later

Parts Information

This is a software-only campaign; there are no associated parts.

Client Notification

American Honda expects to notify owners of affected vehicles at the end of September.

As always, please make sure to check iN VIN status to determine if a particular vehicle is eligible for this product update.

Click [here](#) for a copy of 15-057.

© 2000–2015, American Honda Motor Co., Inc. All Rights Reserved.