

Service

Category Audio/Visual/Telematics

Section	Navigation/Multi Info Display	Market USA	Toyota Supports
---------	-------------------------------	------------	-----------------

Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION	
2013	Avalon, Avalon HV, Camry, Camry HV, Land Cruiser, Prius, Prius PHV, Prius V, RAV4 EV, Sequoia, Venza		
2014	Avalon, Avalon HV, Camry, Camry HV, Land Cruiser, Prius, Prius PHV, Prius V, RAV4 EV, Venza		
2012	Camry, Camry HV, Prius, Prius PHV, Prius V, RAV4 EV		
2015	Land Cruiser, Prius, Prius PHV		

SUPERSESSION NOTICE

The information contained in this bulletin supersedes SB No. T-SB-0006-13.

• Applicability has been updated to include 2015 model year Land Cruiser, Prius & Prius PHV vehicles.

Service Bulletin No. T-SB-0006-13 is Obsolete and any printed versions should be discarded. Be sure to review the entire content of this bulletin before proceeding.

REVISION NOTICE

September 30, 2016 Rev1:

• Required Tools and Equipment has been updated to include a NEW USB Drive Map Update.

Any previous printed versions of this bulletin should be discarded.

Introduction

Toyota models equipped with the Premium HDD Navigation (AVN/AW-EMV) System will periodically require an update to the Gracenote® Database. Gracenote® includes detailed information for songs (e.g., Genre, Artist, Song Title, Album Name, etc.). The Gracenote® update will be included on the "USB Drive Navigation Map Update" SST. A Gracenote® update MUST be performed before a Navigation Map Update. A Navigation Map Update is NOT required to complete the Gracenote® update. Use the process described in this bulletin to perform the update.

Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
N/A	Not Applicable to Warranty	Ι	-	Ι	—

Required Tools & Equipment

SPECIAL SERVICE TOOLS (SST)	PART NUMBER	QTY
USB Drive Navigation Map Update – Denso*	<u>TOYD-HDD07-16</u>	1

* Essential SST.

NOTE

Additional SSTs may be ordered by calling 1-800-933-8335.

Update Procedure

1. Cycle the ignition ON (Engine/Hybrid/EV system OFF).


NOTE

- Vehicles WITHOUT Smart Key system: Turn the ignition key to the "ON" position.
- Vehicles WITH Smart Key system: Press the "Engine Start Stop" switch 2 times with the brake pedal released.
- 2. Insert the USB Drive SST into the USB port of the vehicle (usually located under the navigation head unit, center console/armrest, or glove box).

Update Procedure (Continued)

3. Press the *Setup* button on the navigation head unit.

Figure 1.



4. Select *General* on the navigation screen.

5. Press the down arrow and then select *Gracenote® Database Update.*

Figure 2.



Figure 3.



Update Procedure (Continued)

6. Select Update.

7. Select Yes.

8. Gracenote® Database Update will begin automatically.

NOTE

This process will take about 2 minutes.

9. The head unit will display the NEW Gracenote® version upon completion.

The head unit is now ready for a Navigation Map Update (if desired).

Figure 4.




Figure 5.




Figure 6.

Gra	cenote Database Update
	Updating Gracenote database
•	. Please do not eject or remove the update media.
	. Please do not turn the vehicle off.
gracenot	· .

Figure 7.

