## On-car analysis list from April 3rd, 2017 please contact VW Helpline before attempting repair

	Models	MY	Engine	<b>Transmission</b>	Topic	Customer Complaint
Powertrain	Passat	14-17	1.8T (CPKA/CPRA)	All	MIL-on P2407 (10/21/2016)	MIL-on fault P2407 in the ECM (untouched vehicles)
	Touareg	16-17	All	All	Coolant leak from coolant pump (3/1/2017)	Coolant leak from the coolant pump (untouched vehicles)
	Passat, Beetle, Jetta, Golf/GTI, Sportwagen	15-17	1.8T & 2.0T EA888 Gen 3	All	Oil pressure warning with P164D (4/3/2017)	Oil pressure warning with P164D in the ECM (Must have fault in the ECM) (No oil must be present in connector)
Chassis	Jetta	16-17	All	All	Rear Brake Caliper (1/23/2017)	Rear brake noise, dragging, excessive dust  (untouched vehicles)
	Jetta	17	All	All	Brake Hissing (3/7/2017)	Hissing noise when pressing the brake pedal (untouched vehicles)
	GTI	16-17	All	6 Spd Standard	Clutch pedal squeak (3/1/2017)	Customer states the clutch pedal squeaks when operated (after VIN 3VWYT7AU0GM068470)
Body	Passat	16	All	All	Instrument Panel Noise (9/2/2016)	Instrument panel noise (untouched vehicles after VIN HC011431)
	Passat	16 - 17	All	All	Trunk latch (release) inoperative (1/25/2017)	Trunk latch will not release with key fob, button in the door, on the trunk or with easy open feature (foot release).
	Golf/GTI	16 - 17	All	All	Sunroof Squeak/Rattle (2/13/2017)	Sunroof squeaks/rattles with the sunroof in closed position
	Jetta, Beetle	16 - 17	All	All	A/C Inoperative (3/15/2017)	A/C inoperative, compressor found to be locked up (compressor has to be seized) (untouched vehicles)
	Passat	16-17	All	All	Door Noise (9/2/2016)	Door(s) noise (untouched vehicles after VIN GC052150)