On-car analysis list from June 6th, 2014 please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Touareg, Beetle, Jetta, Passat	2014-2015	1.4T, 1.8T, 2.0L (Jetta ONLY), 2.0T, 2.5L (Jetta ONLY), 3.0L		EVAP leak / EVAP circuit related faults, perform GFF, if GFF fails or does not provide a resolution contact the VW Technican Helpline	
Body	Jetta	14	All	All	Car -Net Button	Car-Net button fell into the overhead console housing
Electrical	No Current Topics					
Chassis	No Current Topics					