



Technical Tip

Topic	91-17-02TT - MIB2 5F Module Rearview Camera Brightness Adjustments
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Volkswagen
Date	March 31, 2017

Condition:

ATTENTION:

**THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.
TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.**

MIB2 5F Module Rearview Camera Brightness Adjustments

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Golf, Golf R, eGolf, GTI, Sportwagen, Jetta, Passat, CC, Beetle, Tiguan	2017	All	All	All	All

Technical Background

When trying to adjust the brightness on a 2017 vehicle equipped with a MIB2 infotainment system, the adjustment menu may not populate when pressing the menu button.

Service



Place the vehicle in reverse with your foot on the brake to allow the rearview camera to activate.



Select the menu button, it will disappear.



Slowly move your hands towards the infrared bar and the menu should populate. Note that you may have to place your hand on the shifter and then back up to the infrared bar.





Select the menu option at the bottom of the screen.



Select the wanted adjustment and use the slider to make the needed adjustment.

Additional Information

Revision History		
Revision Number	Released Date	Reason For Update
2047405/1	3/31/17	Original publication.

© 2017 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.