


Timing Plate Flange Screw
D13
VAH, VHD, VN

FSB 215-003, Timing Plate Flange Screw

(May 2015)

An improved flange screw with pre-applied locking compound (patch-lock) was introduced in production on April 27, 2015 for VOLVO D13 engines. In the event that the timing plate is removed, replace all 29 MP8*25 timing plate screws with screw part number 994447. Torque procedures remain the same as listed in specifications.



W2005945