



# Tech Tips

TT 91-16-10

Date: June 24, 2016

2016-2017 Golf, GTI, Golf R, Sportwagen, eGolf, Passat, Jetta, CC, Tiguan, Beetle, Beetle Convertible - Display Reads "Please insert a data storage device with valid navigation data" DTC B136CF2: "Navigation System Navigation Database not Enabled" may also be stored

**February 3, 2017: Update to Information.**

It is possible that the wrong version navigation SD card is with the car. Also, when replacing a radio or J794, the new unit may require a different version navigation SD card. There are currently 4 part # suffixes available, "R", "AC", "B" and "BB". Install the other suffix SD card that is currently with the car, clear any faults in address word 5F and perform a hard reboot on the radio (hold radio power down for 10-20 seconds) to restore navigation function. **Always refer to ETKA for the latest part number information.**