

Tech Tips

TT 01-17-02

Date: February 3, 2017

2015 Jetta, Beetle, Beetle Convertible, Passat, Golf, Golf Sportwagen - 23Q3 Software Update Reference

When performing the 23Q3 Software Update, it is imperative that Bluetooth and WiFi connections **ARE NOT** utilized as it will result with incomplete programming and the potential for module damage. All connections must be hard wired. Failure to follow this procedure could result in **NON-PAYMENT** for a warranty claim.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.