

[Next Unread Message](#)

View Message

Sent on 07 11 2014 **Expires on** 07 25 2014
From Acura Parts, Service & Technical Division, Campaign Administration
Subject Safety Recall: 2013-14 ILX Headlight Overheats Q&A File

DATE: July 11, 2014

TO: All Acura Sales, Service & Parts Managers and Personnel
FROM: Acura Parts, Service & Technical Division, Campaign Administration

RE: Safety Recall: 2013-14 ILX Headlight Overheats Bolts Q&A File

On June 13, 2014, Acura notified NHTSA of a **Stop Sale** order and **Safety Recall** for some 2013-14 ILX vehicles. Please refer to the attached Q&A File for additional details related to this Safety Recall.

Click [here](#) for the Q&A File in PDF format.

© 2000–2014, American Honda Motor Co., Inc. All Rights Reserved.