

Classification:

Reference:

COPYRIGHT© NISSAN NORTH AMERICA, INC.

Date:

BT17-016a

ITB17-043a

January 26, 2018

MOTION ACTIVATED LIFTGATE STICKER

This bulletin has been amended to add model years to the Applied Vehicles and to update the part number in the Parts Information. Please discard the previous version of this bulletin.

APPLIED VEHICLES: 2017-2018 QX60 (L50) (with deluxe technology package)
 2017-2018 QX60 Hybrid (L50) (with deluxe technology package)

SERVICE INFORMATION

Applied vehicles equipped from the factory with a Motion Activated Liftgate should also have a Motion Activated Liftgate Sticker applied to the back door window glass.

DO NOT remove this sticker during PDI, or when the vehicle is washed, or any other time the vehicle is in inventory.

NOTE:

- Motion activated liftgate sticker is **only** to be removed by the customer.
- Replacement stickers can be obtained from your parts department if damaged or missing.



Figure 1

PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY
Motion activated liftgate sticker	81990 – 9NP0A	1

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.