



[Traduire](#)

[Printable View](#)

Roadster 2012-13 en Can-Am Roadster - Fuel Cap Replacement

Rate This Article

(Average Rating: No Rating)

Version 1

Language

English

[Show Properties](#)

⚠ WARNING

All involved customers must be notified, all involved units must be corrected as per instructions herein.

Product: **Roadster**

Bulletin type: **Safety Campaign**

Bulletin no: **2012-13** (rbg2012-013 en AP)

Revision no:

Revision date:

Campaign no.: **2008-0011**
2009-0007
2010-0015
2011-0019
2012-0013

Publication date: **December 21, 2012**

Subject: **Can-Am™ Roadster - Fuel Cap Replacement**

Year	Model	Model number	Serial number
2008	GS Series	All	All
2009	GS Series		
2010	RS Series RT Series		
2011	RS Series RT Series		
2012	RS Series RT Series		

PROBLEM

The fuel cap may not seal properly the fuel tank filler neck. Fuel vapors in the presence of an ignition source could result in a fire.

SOLUTION

Install new improved fuel cap.
 Discard the old one.

REQUIRED PARTS

Please order fuel cap through the normal channel.


description	Part number	QTY

PROCEDURE

Remove and discard vehicle's fuel cap.

Install the new improved fuel cap.

NOTE: For reference, please see below pictures that will help you identify the new fuel cap which has a reddish color seal AND a different size handle.



WARRANTY

Submit a warranty claim using the following information.

For claiming procedure, refer to the *DEALER/DISTRIBUTOR WARRANTY GUIDE*.

Campaign Claim

Campaign Number	2008-0011 2009-0007 2010-0015 2011-0019 2012-0013
Claim Type	Campaign Claim
Action	Repair
Flat Rate Time	0.3 hour

Click in the REPAIR check box while completing your claim in BOSSWeb.



Campaign Activation

Campaign activation procedure if unit is eligible but does not appear in the recall on BOSSWeb.

For US and Canadian Dealers:

If an eligible vehicle does not appear in the recall on BOSSWeb, send a e-mail to www.warranty@brp.com including the following information:

- SUBJECT: Fuel Cap Recall Activation
- Serial number of the unit
- Customer name.

BRP will activate the unit in the campaign and will return a confirmation e-mail.

When receiving this confirmation, you will be able to claim this recall.

When receiving the commitment, you will be able to claim the credit.

For Dealers Outside of United States of America and Canada

Contact your regional after sales office for specific instructions.

Obsolete Fuel Cap

Please discard all obsolete fuel caps (P/N 709 000 182) that you have in inventory.

Process a Parts Claim (from inventory) for credit of obsolete fuel cap.

IMPORTANT: To be eligible for the credit, your claim must be received before April 30th, 2013.

[Dealer and owner letters.pdf](#)