



GROUP

Chassis

MODEL

2017-2018MY  
Sportage (QL)

NUMBER

PS546

DATE

March 2018



## TECHNICAL OPERATIONS

**SUBJECT:** ELECTRONIC STABILITY CONTROL SELF-CHECK NOISE

This Pitstop provides information regarding a concern related to a single faint 'thud' type noise heard from the engine compartment at speeds of 18-20 MPH after initial start-up. Be aware that the Electronic Stability Control (ESC) system performs it's self-check under these conditions. This single faint 'thud' type noise is normal and indicates that the ESC is functioning properly.

