# DISTRIBUTE TO: ☑ Service Manager ☑ Warranty Administrator



### Warranty Policy Bulletin

No.: Date: POL15-02 09/21/15

Page:

1 of 2

## SUBJECT: CLAIM SUBMISSION PROCEDURES FOR CUSTOMER-REPORTED UNINTENDED BRAKING

To achieve the goal of making "Ever Better" vehicles, Toyota has developed a process to address reports of suspected Unintended Braking (UB). Please follow the claim submission procedure below in the event a customer reports a concern specifically related to UB or claim to have experienced UB.

#### Claim Submission Procedures

Claims may be submitted for a General Inspection/Concern OR Suspected Unintended Braking (UB) Event Inspection.

NOTE: Only 1 opcode/claim allowed per customer concern. Please make sure to select the appropriate opcode when submitting an inspection claim.

#### General Inspection/Concern Only

1) The customer has <u>not</u> reported a suspected Unintended Braking event but is concerned about their vehicle.

If a customer refuses to bring their vehicle in for inspection, the dealer has the option to tow the vehicle in. Since this is an inspection for a concern related to unintended braking, and not an actual incident, alternate transportation is not necessary due to the short inspection process. If there are extenuating circumstances, a rental may be provided with DSPM authorization.

Claim Type	Opcode	Description	Time	Z Time	OFP	T1 /T2 Codes	Goodwill	Allowable Sublets*	Authorization
		General Inspection or Concern Only:					Yes (Check the	*Only for extenuating circumstances	DSPM Auth Required
Regular	CUB001	Customer has not reported a suspected UB event but is concerned about vehicle	0.4	Not Allowed	CUSTM- SATIS	99	Goodwill box and enter Goodwill Comments)		

Please ensure this electronic bulletin is printed and distributed to those designated as well as any other appropriate personnel.

#### Suspected Unintended Braking (UB) Event Inspection

2) The customer has reported a suspected Unintended Braking event.

Please make sure to include the TAS case number in the Authorization Information section of the claim for this type of inspection. Claims submitted without the TAS case number will be returned for correction.

Claim Type	Opcode	Description	Time	Z Time	OFP	T1 /T2 Codes	Goodwill	Allowable Sublets	Authorization
Regular	UBB001	Suspected UB Event Inspection: Customer has reported a suspected UB event	0.7	Allowed	CUSTM- SATIS	99	Yes (Check the Goodwill box and enter Goodwill Comments)	Rental (RT), Towing (TW)	DSPM Auth Required TAS Case # Required

#### **Helpful Tips**

- Please enter a clear C/C/R which reflects the customer's concern, whether the claim is for a general inspection to evaluate the vehicle or if the customer has claimed a suspected UB event.
- TAS case number information is required if using opcode UBB001.
- Use correct sublet types if submitting for Rental (RT) or Towing (TW).
- If a customer has claimed a suspected UB event with an associated accident, property damage, etc., please walk the customer through the process of contacting the Toyota Customer Experience Center (1-800-331-4331) to begin the investigation process.