

Subject

Market

Entune/NAV/Map Update and Upgrade USB Directory

USA

Service Category

Section

Audio/Visual/Telematics

Navigation/Multi Info Display

Applicability

Multiple Vehicles

APPLICABLE VEHICLES

| | | | |
|-----------|--------------|-----------|---------------|
| 2013-2015 | Highlander | 2012-2015 | Camry |
| 2012-2015 | Prius | 2012-2015 | Tundra |
| 2012-2015 | Sienna | 2013-2015 | Avalon HV |
| 2012-2014 | RAV4 EV | 2012-2015 | Prius V |
| 2013-2015 | Land Cruiser | 2012-2015 | 4Runner |
| 2012-2015 | Sequoia | 2013-2015 | Avalon |
| 2012-2015 | RAV4 | 2012-2015 | Venza |
| 2012-2015 | Prius PHV | 2012-2015 | Tacoma |
| 2012-2015 | Prius C | 2013-2015 | Highlander HV |
| 2012-2015 | Corolla | 2012-2015 | Camry HV |




CONDITION

Since MY 2011, several different update or upgrade USB SSTs have been issued for Toyota audio and navigation systems.

Refer to the chart below for a comprehensive list of all current and previously issued USB SSTs and their applicability.

RECOMMENDATIONS

The following chart lists all active and superseded USB update/upgrade SSTs for Toyota vehicles:

| Head Unit Manufacturer | Part Number | Software Version | Applicable Model | Description |
|------------------------|--|--|--|--|
| PANASONIC | 01033-PANSC-15A  | 01018A 01012E 010197 01012A 0101D1 01014E | 14-15 - 4Runner, Highlander, Highlander, Tacoma, Tundra, Sequoia 15 - Avalon, Avalon HV, Prius V, Sienna, Venza | Software upgrade. See linked reference #1 |
| FUJITSU TEN | 01007-FJTSU-13A  | 0.0403 | 13 RAV4 | Software upgrade. See linked reference #2 |
| FUJITSU TEN | 01035-FJTSU-15A  | BU.70.27 BU.38.45 DU.70.64 AU.70.64 AU.38.74 | 14-15 - Corolla, RAV4 14.5 - Camry/Camry HV 15 - Camry, Camry HV, Prius C | Software upgrade. See linked reference #3 |

Subject:

Market:

Entune/NAV/Map Update and Upgrade USB Directory

USA

Applicability:

Multiple Vehicles

RECOMMENDATIONS

| Head Unit Manufacturer | Part Number | Software Version | Applicable Model | Description |
|------------------------|--|------------------|--|--|
| PIONEER | 01026-PIONR-14A  | 0831 | 14 4Runner, Highlander, 14.5 Camry | Software upgrade. See linked reference #4 |
| Harman Becker | 01018-HBEKR-14A  | 3.2.0 | 12-13 4Runner 13-14 Avalon/ Avalon HV 12-14 Camry/Camry HV 12-13 Corolla 13 Highlander/ Highlander HV 12-14 Prius series 12-13 RAV4 12-13 Tacoma 13-14 Venza | Firmware update for Toyota vehicles with Display Audio and Extension Box. See linked reference #5 |
| Harman Becker | TOYH-EXT01-13  | 3.2.0 | | Navigation map update data for Toyota vehicles with Display Audio and Extension Box. Will also update head unit firmware to version 3.2.0. Refer to T-SB-0005-13. |
| DENSO | 01003-DENSO-12A  | V6673170 | 12 Camry/Camry HV 12 Prius V | Software upgrade. Refer to T-SB-0096-12. |
| DENSO | 01006-DENSO-13A  | V6613650 | 13 Land Cruiser | Software upgrade. Refer to T-SB-0044-13. |
| DENSO | 01008-DENSO-13C  | VB503150 | 12-13 RAV4 EV | Software upgrade. Refer to T-SB-0082-13. |
| DENSO | TOYD-HDD07-14  | -- | 13-14 Avalon/Avalon HV 12-14 Camry/Camry HV 13-14 Land Cruiser 12-14 Prius Series 12-14 RAV4 EV 13 Sequoia 13-14 Venza | Gracenote and navigation map updates. For Gracenote and map update refer to T-SB-0007-14. For Gracenote update only refer to T-SB-0006-13. |

Subject

Entune/NAV/Map Update and Upgrade USB Directory








Market

USA

Applicability

Multiple Vehicles

[Obsolete]

| Head Unit Manufacturer | Part Number | Software Version | Applicable Model | Description |
|------------------------|---|----------------------------|---|--|
| Harman Becker | 01001-HBEKR-11A  | 1.8.4 | OBSOLETE: See 01018-HBEKR-14A | Firmware update for Toyota vehicles with Display Audio and Extension Box. |
| Harman Becker | 01002-HBEKR-12B  | 2.1.0 | OBSOLETE: See 01018-HBEKR-14A | Firmware update for Toyota vehicles with Display Audio and Extension Box. * Red USB provided to customer for self-update |
| Harman Becker | 01004-HBEKR-13A  | 2.2.0 | OBSOLETE: See 01018-HBEKR-14A | Firmware update for Toyota vehicles with Display Audio and Extension Box. |
| Harman Becker | 01010- HBEKR-13B  | 3.1.0 | OBSOLETE: See 01018-HBEKR-14A | Firmware update for Toyota vehicles with Display Audio and Extension Box. |
| Harman Becker | TOYH-EXT01-12  | 2.2.0 | OBSOLETE: See TOYH-EXT01-13 | Navigation map update data for Toyota vehicles with Display Audio and Extension Box. Will also update head unit firmware to version 2.2.0. |
| PANASONIC | 01016-PANSC-13A  | 010179 010183 0101A1 | OBSOLETE: See 01033-PANSC-15A | Software upgrade. |
| PANASONIC | 01021-PANSC-14A  | 01017B 010185 0101A5 | OBSOLETE: See 01033-PANSC-15A | Software upgrade. |

Subject







Entune/NAV/Map Update and Upgrade USB Directory

Market

USA

Applicability

Multiple Vehicles

| | | | | |
|----------------|--|----------------------------------|---|---------------------------------------|
| PANASONIC | 01025-PANSC-14B  | 010180 01018B 0101B1 | OBSOLETE: See 01033-PANSC-15A | Software upgrade. |
| FUJITSU TEN | 01017-FJTSU-13B  | BU.30.18 AU.30.26 | OBSOLETE: See 01035-FJTSU-15A | Software upgrade. |
| FUJITSU TEN | 01027-FJTSU-14A  | BU.70.06 DU.70.09 AU.70.09 | OBSOLETE: See 01035-FJTSU-15A | Software upgrade. |
| DENSO | 01008-DENSO-13B  | VB503150 | OBSOLETE: See 01008-DENSO-13C | Software upgrade. |
| DENSO | TOYD-HDD07-12  | -- | OBSOLETE: See TOYD-HDD07-14 | Gracenote and navigation map updates. |
| DENSO | TOYD-HDD07-13  | -- | OBSOLETE: See TOYD-HDD07-14 | Gracenote and navigation map updates. |

LINK REFERENCES

1. [T-SB-0160-14 Rev1: '14-'15 Applicable Toyota Models: Entune Audio Head Unit Software Update \(Panasonic\)](#)
2. [T-SB-0078-13: '13 RAV4: Back-up Camera Displays Incorrect Language in Spanish or French](#)
3. [T-SB-0015-15: '14-'15 Applicable Toyota Models: Entune Audio Head Unit Software Update \(Fujitsu Ten\)](#)
4. [T-SB-0047-14: '14 4Runner, Camry, Camry HV, Highlander, Highlander HV: Entune Audio Head Unit Software Update \(Pioneer\)](#)
5. [T-SB-0051-13 Rev2: '12-'14 Applicable Toyota Models: Abnormal Entune/Navigation Operation for Display Audio \(Non-HDD Type\)](#)