

Service Bulletin

Bulletin No.:


n No.: 17-NA-337 Date: October, 2017

INFORMATION

Subject: All or Some Options May Be Missing from Driver Information Center (DIC) "Info Pages" Menu Due to Them Not Being Selected

Brand:	Model:	Model Year:		VIN:		Engine	Transmission:
		from	to	from	to	Engine:	
Buick	Encore, LaCrosse, Regal	2016	2018				
	Enclave	2018	2018				
Cadillac	ATS, CT6, CTS	2016	2018				
	ELR	2016	2017				
	Escalade Models	2016	2018				
	XTS	2016	2018				
	XT5	2017	2018				
Chevrolet	Camaro, Corvette, Cruze, Impala, Malibu, Volt	2016	2018				
	Colorado, Silverado, Suburban, Tahoe						
	Equinox	2018	2018				
	Traverse						
GMC	Canyon	2016	2018				
	Sierra, Yukon Models						
	Acadia	2017	2018				

Involved Region or Country	North America and N.A. Export Regions		
Additional Options (RPOs)	Equipped with up-level infotainment system (RPOs IO5, IO6 or UY4)		



Service Procedure



4882878

1. From the Main Menu; Select "Options."



4882898

2. Then scroll Up or down until "Info Pages" Page appears on the screen.



 Click on the Right button to get to the "Edit List" option.



4. "Active Info Pages" Page will appear and the list of all pages that can be activated.





- 5. Scroll Up and Down through the pages to check which ones are active and which ones aren't.
- 6. After activating the checkbox in front of the Info Pages that are desired to be active, go back to the Main Menu, under "Info", and scroll Up and Down to make sure they appear.

Version	1		
Modified	Released October 23, 2017		

GM bulletins are intended for use by professional technicians, NOT a "<u>do-it-yourselfer</u>". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, <u>DO NOT</u> assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION