

Solution K73120837 Thursday, May 3, 2018 10:43:13 PM CEST

NA_MACK_Vehicle_Range

NA_MACK_Vehicle_Ran ge	LR, LEU, MRU, CHU, CXU, GU, TD
Engine family	
Engine family	MP7, MP8, MP10
Emission Standard	
Emission Standard	US16, US15, US14 GHG
** SOLUTION **	
Title (customer effect)	Mack Chassis - Diagnostic Trouble Code (DTC) P0507 Lighting The Malfunction Indicator Lamp (MIL) - US14+OBD13, US14+OBD15, US14+OBD16 Emissions (Non-Common Rail Fuel System), Common Model Years 2015 To 2017
Cause	US14+OBD13, US14+OBD15, US14+OBD16 Emissions vehicles may log DTC P0507.
Solution	Verify the chassis emissions level

• Details can be found in the Product Details box on the Product tab in PTT as seen below:



For US14+OBD13

- Refer to FSB 284-066 Engine Control Module (ECM) and Aftertreatment Control Module (ACM), Reprogramming.
 - This bulletin is current as of 17 April 2018.

For US14+OBD15

- Software improvements have been released to address this code. Refer to the table

below:

Action Required			
ECM	Main Software	Action Required	
MP7 / MP8	Equal or Less Than 22741784	Update to Latest Software	
MP10	Equal or Less Than 22644017	Update to Latest Software	
ACM	Main Software	Action Required	
MP7 / MP8 / MP10	Equal or Less Than 22741796	Update to Latest Software	

For US14+OBD16

-	Refer to	FSB	284-065	Engine	Control	Module	(ECM)	and	Aftertreatment	Control

- Module (ACM), Reprogramming.
 - This bulletin is current as of 17 April 2018.

	If any other symptoms or related codes are present, they will need to be diagnosed before P0507. P0507 will not cause any physical symptoms if it is generated by software.			
Campaign code	FSB284-065, FSB284-066			
Solution visibility	Dealer distribution			
Function(s)/componer	nt(s) affected			
Function affected	FSB , engine , regulation (cruise control/engine speed) , 1 1 0 EMS			
Function Group				
Function Group	28 ignition and control system			
Customer effect				
Main customer effect	engine speed, calibration/programming/pairing/missing operation, diagnostics /methodology, efficiency/abnormal behavior, fault code/display			
Lights/Messages on information display	Driver's information warning pictogram			
Fault code(s)				
OBD 2013 Diagnostic Trouble Codes	P0507			
Conditions				
Vehicle operating mode	when stationary			
Frequency of occurrence of problem	rence of random			
Administration				
Author	RU4469V			
Dealer ID	RU4469V			

Last modified by	RU4469V
Creation date	19-04-2018 18:04
Date of last update	19-04-2018 19:04
Status	Published