



SERVICE BULLETIN

Classification: EL16-039c	Reference: NTB16-100c	Date: May 2, 2018
------------------------------	--------------------------	----------------------

2016-2017 NISSAN CONNECT NAVIGATION SYSTEM SOFTWARE UPDATE

APPLIED VEHICLES: 2016 Altima (L33)
2016 Frontier (D40)
Vehicles built **after** 1N6(*)D0(***)GN 727602 // January 4, 2016
2016 Juke (F15)
2016 Rogue (T32)
2016 Sentra (B17)
2016 Titan XD (A61)
2017 Titan and Titan XD (A61):
Vehicles built **before** 1N6(*)A1(***)HN 521678 // November 28, 2016
Applied Vehicles equipped with navigation system only

This bulletin has been superseded to NTB18-031. Please discard all previous versions of this bulletin.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.