ATTENTION: Dealer Principal, Warranty Manager, Service Manager, Parts Manager

Freightliner Dealers – Ü.S. and Canada Western Star and Sterling Dealers – U.S. and Canada FCCC Dealers – U.S. and Canada Direct Warranty Customers – U.S. and Canada Export Distributors

Daimler Trucks North America LLC

WARRANTY CAMPAIGNS DEPARTMENT

P.O. Box 4090 800-547-0712 Portland, Oregon 97208-4090

> If you have questions about this Letter, please submit your inquiry on the Web using the WSC Link on DTNAConnect

REF #: ICI18-010

Effective: 04/16/2018 Release: 04/16/2018

SUBJECT: SF536 - (Second) Revised Bulletin

This letter is to inform you that a (second) revised bulletin for Field Service Campaign *SF536 FCCC MUX Wiper Control* is available on DTNAConnect. Please print and use the revised bulletin for all work under SF536 from this point forward.

SECOND REVISION: Steps 7 and 9 of the work instructions have been updated. Step 7 – vehicle date has **changed from 2.07 to 2.08**. Step 9 – parameter has **changed from 26-04009-009 to 26-04009-013**.

If you have questions or need further information, contact the Warranty Campaigns Department by submitting an inquiry through the WSC Link on DTNAConnect.