# **SERVICE CAMPAIGN**



## CAMPAIGN BULLETIN Speedometer and Odometer Inaccuracy Voluntary Service Campaign - Expiration Notice

Reference: P0303, P0332 Date: July 18, 2018

Attention: Retailer Principal, Sales, Parts and Service Managers

Campaign ID	Affected Models/Years:	Affected Population:	Retailer Inventory:	SERVICE COMM Expiration date:	Stop Sale In Effect
P0303		NLA	NLA	July 10, 2010	
P0332	MY2007-2008 FX	NA	NA	July 18, 2018	NO

#### \*\*\*\*\* Campaign Summary \*\*\*\*\*

In 2010, INFINITI launched the above Voluntary Service Campaigns on certain MY 2007-2008 INFINITI FX vehicles to offer clients the opportunity to correct the odometer reading and reprogram the electronic module to display speed and record distance on the odometer more accurately, at no charge to the client for parts and labor. Parts and tools specified for these campaigns are no longer available for sale through INFINITI.

These client satisfaction initiatives will no longer be offered and the campaigns are no longer active.

### \*\*\*\*\* What Retailers Should Do \*\*\*\*\*

- 1. Service Comm will deactivate P0303 or P0332 on any unrepaired VINs on July 18, 2018.
  - No further action is required
- 2. Retailers should submit any open claims for these campaigns as soon as possible. INFINITI would like to have all claims submitted by **August 1, 2018**.

#### \*\*\*\*\* Release Schedule \*\*\*\*\*

Repair	• Campaign bulletin <b>ITB10-045 and ITB10-065</b> have been updated to reflect expiration of these voluntary service campaigns. Please discard older copies.	
Owner Notification	No expiration notice is being sent to clients.	