



SUBJECT

DCT Transmission: Oil Leakage Diagnosis

MODEL

E82 (1 Series 135i Coupe)

E88 (1 Series 135i Convertible)

E89 (Z4 sDrive35is)

With option 02TC (DCT transmission)

E90, E92, E93, F80 (M3)

F82, F83 (M4)

F10 (M5)

F12, F13, F06 (M6)

With option 02MK (DCT transmission)

INFORMATION

Incorrect diagnosis of DCT (Double-clutch Transmission) oil leaks may lead to unnecessary part replacements and repeat customer repair visits.

When diagnosing complaints related to DCT fluid leaks, please use the attached diagnostic procedure.

WARRANTY INFORMATION

Not applicable.

ATTACHMENTS

View PDF attachment [**B280114 DCT Oil Leak Diagnosis.**](#)

[Copyright ©2014 BMW of North America, Inc.]