

| | | | |
|-------------------------------------|-------------------------------|------------|--|
| Subject | | Market | |
| Navigation DTC B15E6 Present | | USA | |
| Service Category | Section | | |
| Audio/Visual/Telematics | Navigation/Multi Info Display | | |
| Applicability | | | |
| 14-15MY RAV4 | | | |

APPLICABLE VEHICLES

2014-2015

RAV4

CONDITION

Some 2014 and 2015MY RAV4 vehicles may exhibit a B15E6 DTC in the navigation system. This DTC pertains to a system that is not equipped to US Market vehicles and should be ignored. This DTC has no adverse effects on the operation of the navigation system and should not have a repair attempted.

RECOMMENDATIONS

Please ignore this DTC and do not attempt to diagnose/repair this DTC.

LINK REFERENCES

This Tech Tip does not contain any link references