

## Solution K17039050 Friday, January 4, 2019 5:13:36 PM CET

## **Mack Models**

Mack Models	
Mack Model	$TE-TerraPro\;,\;LR\;,\;LEU\;,\;MRU-TerraPro\;,\;AN-Anthem\;,\;GR-Granite\;,\;PI-Pinnacle\;,\;CHU-Pinnacle\;,\;Axle\;back\;,\;CXU-Pinnacle\;,\;Axle\;front\;,\;GU-Granite\;,\;T\;D-Titan$
Volvo Models	
Volvo Model	VNL, VNM, VNR, VNX, VAH, VHD
** SOLUTION **	
Title	Bendix ACom® - EC80 ESP Controller; ABS And ATC Lights Illuminated, Fault Codes Present After Making Changes, Calibration Or Programming With ACom
Cause	Bendix has found that ACom® version v.6.16.5.0, released on December 12, 2018 is causing fault codes on vehicles following configuration changes, calibration operations, and programming using the ACom software. The ACom version available for download on the Bendix website has been reverted back to v.6.16.4.2.
Solution	If the ABS and ATC lights illuminate with fault codes logged following any operation performed using ACom v.6.16.5.0:
	1. Uninstall ACom from the computer.
	2. Go to the Bendix ACom download site.
	3. Fill in the necessary information, download, and instal ACom version v.6.16.4.2.
	For any further inquiries or assistance needed, contact the Bendix Tech Team at 800-AIR-BRAKE.
	This information is current as of 19 December 2018. The Bendix Tech Team or website should be checked for the latest information concerning this issue.
Internal comments (BO)	1-11042460041
Solution visibility	Dealer distribution
Function(s)/compone	ent(s) affected
Function affected	MID 136 ABS, Bendix, VMAC
Function Group	
Function Group	384 warning system , 593 anti-lock brake (anti-skid)
Customer effect	
Main customer effect	calibration/programming/pairing/missing operation, fault code/display
Lights/Messages on information display	Tractor "ABS" warning light: system fault warning pictogram

## Fault code(s)

US10 Fault Codes	SPN 1045 FMI 2 , SPN 1067 FMI 7 , SPN 1067 FMI 11
Conditions	
Other conditions	after a workshop procedure on the vehicle
Administration	
Author	A241298
Dealer ID	A241298
Last modified by	A241298
Creation date	19-12-2018 14:12
Date of last update	20-12-2018 18:12
Review date	01-03-2019 00:03
Status	Published