

Latest Vehicle Concern Fixes



Programming Modules	I-Pace
<p>Customer Voice:</p> <ul style="list-style-type: none">• Vehicle has various faults and messages on the IPC after programming <p>Actions:</p> <ul style="list-style-type: none">• Although under show room and normal conditions the 12v system is maintained by either the DC/DC converter or as the vehicle charges, the vehicle still requires a 12v battery maintainer when programming, especially when programming HV related modules.• The vehicle should also not be connected to a charger when programming. Much like a regular ICE vehicle, one would not (under normal circumstances) fuel the vehicle whilst programming. Pathfinder does alert when it is absolutely imperative to remove any HV chargers from the vehicle, but it should be assumed that a 12v maintainer is part of normal programming process.	

