

Latest Vehicle Concern Fixes



Check Engine Light with DTC P0420

14-17 Discovery Sport and RR Evoque

Customer Voice:

- The Check Engine Lamp is on.

Technical Description:

- DTC P0420 is stored in the PCM.
- Diagnosis leads to replacement of the catalytic converter.

Status:

- We are currently working to refine our problem definition and are in need of parts for analysis.
- Please raise an EPQR for any repairs performed on these vehicles for DTC P0420.
- Hold any parts replaced for return.

