



Technical Tip

Topic	97-19-01TT - Relay Terminal Locations and Pin Assignments
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Volkswagen
Date	April 5, 2019

Condition

ATTENTION:

**THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.
TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.**

Relay Terminal Locations and Pin Assignments

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Jetta, Golf, GTI, Golf R, Sportwagen, Passat, CC, Beetle, Beetle Convertible, Tiguan, Touareg, Tiguan LWB, Atlas	2016-2019	All	All	All	All

Technical Background

In random applications, relay terminal positions are being noted with a new numeric designation that does not describe the circuits.

Service

Relay terminal numbers are 1 through 5 and correlate with the following circuit functions. 1/86, 2/85, 3/30, 4/87a, 5/87, see figures 1 and 2.




Figure 1




Figure 2

Additional Information

Revision History

Revision Number	Released Date	Reason For Update
2054618/1	4/5/19	Original publication.

© 2019 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.