

# **Technical Service Bulletin**

Technical Service Bulletin: TSB190039

Released Date: 26-Mar-2019

Poor Drivetrain Performance During Warmup Mode: Eaton™ Automated Manual Transmission

## Poor Drivetrain Performance During Warmup Mode: Eaton™ Automated Manual Transmission

## Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

## Contents

#### **Product Affected**

Engine:

• ISX12N CM2380 X120B

Transmission:

• Eaton™ automated manual transmission

#### lssue

Symptom:

- Engine misfire fault codes and/or poor transmission shift performance during warmup mode.
- Transmission stuck in starting gear and/or not shifting gears.
- Transmission fault code 74

Root Cause:

• Engine calibration errors during engine warmup.

#### **Service Instructions**

- An improved engine control module (ECM) calibration revision has been released.
- Reference QuickServe® Online (QSOL) ECM calibration revision history or INSITE<sup>™</sup> electronic service tool calibration revision history to view warrantable update symptoms.
- See Table 1 for ECM calibration code and revisions containing improvements.
- Any ECM calibration released after 7 March 2019 will contain these improvements unless otherwise stated.

Table 1, ECM Calibration Code and Revision							
ECM	Revisio	ECM	Revisio	ECM	Revisio	ECM	Revisio
Code	n	Code	n	Code	n	Code	n
JH1000 1	9	JH1003 1	7	JH1006 1	2	JH1008 1	2
JH1000 2	8	JH1003 2	7	JH1006 2	2	JH1008 2	2
JH1000 3	8	JH1003 3	8	JH1006 3	2	JH1008 3	2
JH1000 4	9	JH1003 4	8	JH1006 4	2	JH1008 4	2
JH1000 7	7	JH1003 5	7	JH1006 5	2	JH1008 5	2
JH1000 8	7	JH1003 6	7	JH1006 6	2	JH1008 6	2
JH1000 9	8	JH1003 7	8	JH1006 7	2	JH1008 7	2
JH1001 0	8	JH1003 8	8	JH1006 8	2	JH1008 8	2
JH1001 1	7	JH1004 3	7	JH1006 9	2	JH1008 9	2
JH1001 2	7	JH1004 4	7	JH1007 0	2	JH1009 0	2
JH1001 3	8	JH1004 5	8	JH1007 1	2	JH1009 1	2
JH1001 4	8	JH1004 6	8	JH1007 2	2	JH1009 2	2
JH1001 9	7	JH1004 7	7	JH1007 3	2	JH1009 3	2

41110000	0010101000	olulou.		

Г

Table 1, E	Table 1, ECM Calibration Code and Revision						
ECM Code	Revisio n	ECM Code	Revisio n	ECM Code	Revisio n	ECM Code	Revisio n
JH1002 0	8	JH1004 8	7	JH1007 4	2	JH1009 4	2
JH1002 1	7	JH1004 9	8	JH1007 5	2	JH1009 5	2
JH1002 2	8	JH1005 0	8	JH1007 6	2	JH1009 6	2
JH1002 5	8	JH1005 5	7	JH1007 7	2	JH1009 7	2
JH1002 6	9	JH1005 6	8	JH1007 8	2	JH1009 8	2
JH1002 7	8	JH1005 7	7	JH1007 9	2	JH1009 9	2
JH1002 8	9	JH1005 8	8	JH1008 0	2	JH1010 0	2

## **Document History**

Date	Details
2019-3-15	Module Created

#### Last Modified: 26-Mar-2019